

Risk Assessment – record of significant findings

Risk assessment for :Mowgli building @ Polyapes.	Assessment undertaken by: Simon Clarke – Volunteer Site Manager
--	---

Step 1 – identify fire hazards

Sources of ignition:	Sources of fuel:	Sources of oxygen:
Cooker; general electrical	gas; timber; bedding; curtains;	atmosphere
equipment eg kettle; burco;	furniture	
water heater		

Step 2 – people at risk
Occupants of the building

Step 3 – Evaluate, Remove, Reduce and protect from risk

(3.1) Evaluate the risk of the fire occurring	Minimal chance of fire
(3.2) Evaluate the risk to people from a fire	Little risk to staff or visitors as the single storey
starting on the premises	building sits on its own with escape routes
	marked. Mains connected smoke/heat alarms
	are fitted with battery back-ups.
	Luminous signs, night lights/emergency lighting
	inside and outside ensure safe evacuation, day
	and night.
	Wheelchair routes marked
	No open fires close enough to consider a risk
(3.3) Remove and reduce possible hazards that	Ensure all fire sources are kept clear from
may cause a fire.	combustible materials e.g make sure cooker is
	kept clear from tea towels and food packaging
	etc.
(3.4) Remove and reduce the risks to people	Building has regular fire alarm checks. Fire
from a fire	blanket in kitchen area subject of annual checks
	as required. Fire action plans in place and
	posted on notice board in hall, bedrooms, toilet
	and kitchen.